

SECRET

| ROUTING |      |   |    |
|---------|------|---|----|
| 1       | MD   | 4 | OD |
| 2       | IL   | 5 |    |
| 3       | DIFA | 3 | /  |

1258Z 17 OCT 63

TO DIRECTOR

FROM [ ] 25X1A

ACTION: OSA 1-20

INFO :

BFB  
CD  
Intel  
RB

ROUTINE

TOR: 1328Z 17 OCT 63

IN 96142

25X1A TO [ ] INFO [ ] 25X1A 25X1A CITE [ ] 0279

25X1A [ ] THREE

25X1A REF [ ] 4962

25X1A 1. [ ] IS ALSO IN NEED OF NEW PILOT TRANSPORT VAN. DUE TO AGE AND LONG USE OF PRESENT VAN IT REQUIRES VERY FREQUENT MAINTENANCE AND PARTS ARE BECOMING INCREASINGLY DIFFICULT TO OBTAIN. BASE MAINTENANCE HAS REACHED THE POINT THAT THEY CAN NO LONGER PROVIDE US ADEQUATE SUPPORT ON THIS VEHICLE.

25X1A 2. [ ] RECOMMENDS TYPE REPLACEMENT VEHICLE SIMILAR TO THAT ONCE CONSIDERED WHILE HE WAS ASSIGNED HQ.

END OF MESSAGE

DOCUMENT NO. [ ]  
NO CHANGE IN CLASS. [X]  
☐ DECLASSIFIED  
CLASS. CHANGED TO: TS & B 2011  
NEXT REVIEW DATE: [ ]  
AUTH: HR 13-2  
DATE: 13 JUL 1991 REVIEWER: 064540

SECRET

GROUP 1  
Excluded from automatic  
downgrading and  
declassification

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Copy No